

COUNCIL COMMUNICATION

AGENDA TITLE: Heritage School Vicinity - Various Traffic Studies

MEETING DATE: March 20, 1996

PREPARED BY: Public Works Director

RECOMMENDED ACTION: That the City Council review the following traffic studies performed in the

vicinity of Heritage School and take the appropriate action.

BACKGROUND INFORMATION: Following a fatal traffic accident at the intersection of Central Avenue

and Eden Street, involving Heritage School students, the City met with Lodi Unified School District (LUSD) administration to discuss concerns. As a result of that meeting and requests from the public,

the following issues were evaluated:

Multi-way Stop Control Study

- Garfield Street at Eden Street
- Central Avenue at Eden Street

Adult Crossing Guard Study

- Garfield Street at Eden Street
- Central Avenue at Eden Street
- Cherokee Lane at Eden Street

Additional School Crosswalk Review

- Garfield Street at Eden Street
- Central Avenue at Eden Street

Additional School Area Signing Review

Heritage School Vicinity

The evaluation includes a review of previous actions performed in the Heritage School area, review of current conditions, and new studies performed as indicated.

CURRENT CONDITIONS

Heritage School is located in the block east of Garfield Street and north of Eden Street. The school attendance area is bounded on the north by Lodi Avenue, Kettleman Lane to the south, Southern Pacific Railroad tracks to the west, and Highway 99 to the east (Exhibit A). This year-round school accommodates up to 600 kindergarten through sixth grade students. With the exception of special education students, busing is not provided by LUSD. Congestion at the school site is highest at the intersection of Garfield and Eden streets, which is located at the southwest corner of the school grounds. The City has performed several studies in the Heritage School vicinity. Exhibit B is a chronological list of studies performed and actions taken.

APPROVED:

H. Dixon Flynn -- City Manager

03/13/96

Heritage School Vicinity - Various Traffic Studies March 20, 1996 Page 2

NEW STUDY RESULTS

Multi-way Stop Control Study

The City uses State of California Department of Transportation (Caltrans) guidelines when considering the installation of multi-way stop controls. These guidelines basically consider traffic and pedestrian volumes and the number of correctable accidents occurring in a recent 12-month period.

Garfield Street at Eden Street (Exhibit C) - Traffic at this intersection is controlled by stop signs on Eden Street at Garfield Street. Available accident records for the 4-year period from 1992 through 1995 indicate there has been one accident correctable with the installation of multi-way stop controls. There were no correctable accidents over the past 12-month period. This left-turn versus through accident did not involve pedestrians. Recent traffic volume counts performed at Garfield and Eden streets are 1,420 and 960 vehicles per day, respectively. Vehicle and pedestrian volumes are below the minimums indicated in the guidelines. Multi-way stop controls are not warranted at this intersection.

Central Avenue at Eden Street (Exhibit D) - Traffic at this intersection is controlled by stop signs on Eden Street at Central Avenue. Available accident data for the 4-year period from 1992 through 1995 indicated there were two accidents (1993 and 1994) correctable with the installation of multi-way stop controls. Neither of these two right-angle accidents involved pedestrians. The recent pedestrian accident involved a turning vehicle striking three pedestrians crossing Eden Street. Since the driver indicated the rising sun obscured his vision, it cannot be determined if this accident would be considered correctable. Recent traffic volume counts performed at Central Avenue and Eden Street are 5,375 and 750 vehicles per day, respectively. Vehicle and pedestrian volumes are below the minimums indicated in the guidelines. Multi-way stop controls are not warranted at this intersection.

Adult Crossing Guard Study

Caltrans guidelines are also used when considering the placement of Adult Crossing Guards. These guidelines consider vehicle volumes and the number of school-aged pedestrians crossing during two 1-hour periods during the day when pedestrians are going to and from school. The number of vehicles required by the guidelines varies depending on the type of traffic control existing at the intersection. At uncontrolled intersections, 40 school-aged pedestrians and 350 vehicles are needed to satisfy these guidelines. These guidelines must be satisfied for each of the two 1-hour survey periods.

Garfield Street at Eden Street - Traffic and pedestrian volumes performed at this intersection indicate that during the morning count there were 103 pedestrians and 130 vehicles. In the afternoon count, 124 pedestrians and 116 vehicles were recorded. Caltrans guidelines for an adult crossing guard are not satisfied at this intersection due to insufficient vehicle volumes, similar to previous studies.

Central Avenue at Eden Street - Traffic and pedestrian volumes performed at this intersection indicate that during the morning count there were 19 pedestrians and 245 vehicles. In the afternoon count, 66 pedestrians and 296 vehicles were recorded. Caltrans guidelines for an adult crossing guard are not satisfied at this intersection due to insufficient vehicle and pedestrian volumes, similar to the previous study.

Cherokee Lane at Eden Street - Staff has not performed an Adult Crossing Guard Study at this intersection because the only residential area where students would be expected to cross. Cherokee Lane is adjacent to the traffic signal at Hale Road. An Adult Crossing Guard currently assists students crossing at this intersection. While no crossing is completely safe, the benefits of crossing at Hale Road far exceed crossing at Eden Street, even with the assistance of an Adult Crossing Guard. Placing an Adult Crossing Guard at Eden Street would only encourage students to cross at this location. Heritage School administration has indicated they will again notify students and parents to cross Cherokee Lane at Hale Road instead of Eden Street.

CHERITAG.DOC 3/13/96

Heritage School Vicinity - Various Traffic Studies March 20, 1996
Page 3

Additional School Crosswalks

The City has reviewed the locations of school crosswalks at the intersections of Central Avenue at Eden Street and Garfield Street at Eden Street. According to the California Vehicle Code, crosswalks exist at all intersections whether they are indicated by painted lines (marked) or not (unmarked). Studies indicate that while more pedestrians use marked than unmarked crosswalks, more accidents occur in the marked crosswalks. These factors indicate that marked crosswalks should be used as pedestrian guides and not as safety devices. The existing crosswalks at these intersections have been placed to guide school pedestrians to the intersection of Garfield and Eden streets, where Student Crossing Patrols can assist students crossing. The routes to Heritage School are shown on the "Suggested Route to School" map (Exhibit E). Similar maps are prepared by the City for all elementary schools and provided to LUSD for distribution to students and parents.

Additional School-Area Signing

Caltrans guidelines are used when placing school area signing. These guidelines provide consistency, which assists drivers by letting them know what they can expect at various schools. Major concerns regarding school-area signing is oversigning and placing school signs too far from school sites. Installing too many signs can lead to driver confusion and disrespect. Signs placed too far from the school site can lose effectiveness, particularly when school-related activity is infrequent.

DISCUSSIONS/RECOMMENDATIONS

While the City is, and has always been, very concerned about the safety of pedestrians, the facts are the needs of pedestrians and drivers are diverse. Since the mixture of pedestrians and vehicles are here to stay, the needs of each must be balanced. While many believe pedestrian safety issues can be resolved by adding more traffic control devices, such as stop signs, in many cases improperly used traffic control devices can lead to increased vehicle and pedestrian accidents. While most drivers are reasonable, when confronted with unreasonable restrictions, flagrant violations may result. The combination of the false sense of security that stop signs portray to pedestrians and the contempt drivers feel for having to stop unnecessarily can create a more hazardous condition than previously existed. Based on the study results and other factors indicated, staff's recommendations are as follows:

Multi-way Stop Controls

At intersections of major and minor streets, such as Central Avenue at Eden Street, the major street is typically not controlled. Major streets, such as Central Avenue, are designed to carry larger volumes of traffic as expeditiously as reasonable. It would not be practical to stop all of the vehicles on Central Avenue at every minor street crossing, especially due to the relatively short period of time the students are using the crossing. Multi-way stop controls are not recommended at the intersection of Central Avenue and Eden Street.

At minor street intersections, such as Garfield Street and Eden Street, traffic controls are either not used or are placed on the street carrying the least amount of traffic. This allows the street with the majority of traffic to flow uninterrupted. Based on existing traffic volumes, the traffic control is on the correct street. Since overall traffic volumes at the intersection are low, the use of multi-way stop controls would create a minimal amount of overall delay for drivers. However, traffic volumes and pedestrian activity are greatest at the times when students are going to and from school. Due to increased traffic and pedestrian activity during this time period, installing multi-way stop controls at this intersection would not reduce congestion, but increase the length and severity of congestion due to the additional unnecessary stops that would be required by drivers on Garfield Street. *Multi-way stop controls are not recommended at the intersection of Garfield and Eden streets*.

CHERITAG.DOC 3/13/96

Heritage School Vicinity - Various Traffic Studies March 20, 1996 Page 4

Adult Crossing Guards

Caltrans guidelines for Adult Crossing Guards are not met at either of these intersections. Both vehicle and pedestrian volumes are below the guidelines at the intersection of Central Avenue and Eden Street. At the intersection of Garfield and Eden streets, pedestrian activity is significant, but vehicle volumes are low. Due to low vehicle volumes, staff surveyed both intersections during periods of light rain when students are more likely to be driven to school; vehicle volumes still remained low. Even though State guidelines for adult crossing guards are not satisfied at these intersections, it does not prohibit LUSD from placing an Adult Crossing Guard at these or any location. The funding of all Adult Crossing Guards has been entirely the responsibility of LUSD since 1993 due to changes in the legislation. Training of Adult Crossing Guards is performed by LUSD as authorized by the Police Chief.

An adult volunteer is currently assisting at the intersection of Garfield and Eden streets. Per Section 10.12.030 of the Lodi Municipal Code, only persons authorized by the Police Chief can direct traffic. Since the adult at this intersection has not been trained, LUSD has been informed of the need to correct this problem. In addition, we have discussed the removal of the student patrol that previously assisted crossing at Garfield and Eden streets. LUSD is also looking into this matter.

Additional School Crosswalks and School-Area Signing

Based on a review of school crosswalks in the area, staff feels they are properly located for the purpose of guiding students. Also, based on Caltrans guidelines, all of the required school-area signing is installed. Studies indicate that arbitrarily adding crosswalks or pedestrian crossing signs may increase pedestrian-related accidents by reducing the amount of caution pedestrians feel is needed due to the false sense of safety provided by these signs and markings. Staff does not recommend that additional school crosswalks or school-area signing be installed.

As an informational note, traffic engineering staff has recently applied for a grant to increase the level of pedestrian and bicycle safety for school-aged children. In many cases, pedestrian and bicycle accidents are caused by poor judgment or inattention, both of which can be corrected by public education; however, this type of education should begin in the home. During our surveys performed adjacent to the school, staff observed several drivers stopping in the roadway or middle of the intersection adjacent to the school to drop off passengers. Pedestrians were also observed crossing diagonally and midblock and bicyclists riding in crosswalks and not obeying traffic controls. Unfortunately, many students were performing these acts at the direction of adults. Staff will also be recommending that educational programs and Police enforcement be performed to address the problems observed.

FUNDING: Not applicable.

Jack L. Ronsko Public Works Director

Prepared by Traffic Engineering Staff Attachments

Attachments

cc: City Attorney
 Police Chief
 LUSD Superintendent
 LUSD Police Services - Biglow
 Police Department CSO Fuhs
 Police Captain Adams
 Associate Traffic Engineer
 Heritage School Principal and Vice Principal
 Concerned Citizens

CHERITAG.DOC 3/13/96

Heritage School Vicinity - Previous Studies and Actions

November 1985

• Central Avenue at Eden Street - studied intersection for adult crossing guard at the request of School District. Caltrans guidelines not satisfied.

December 1987

• Garfield Street at Eden Street - studied intersection for adult crossing guard at the request of School District. Caltrans guidelines not satisfied.

January 1988

• Garfield Street at Eden Street - studied intersection for multi-way stop controls at the request of School District. Caltrans guidelines not satisfied.

January 1988

Garfield Street at Eden Street - installed "no parking" zones adjacent to crosswalks to improve visibility
of student patrols and vehicles.

February 1989

• Heritage School Vicinity - reviewed school area signing for compliance with Caltrans guidelines. All school signing and marking required by Caltrans are installed.

May 1989

• Garfield Street at Eden Street - studied intersection for adult crossing guard and multi way stop controls. Caltrans guidelines not satisfied for either.

• July 1991

 Cherokee Lane at Hale Road - studied intersection for adult crossing guards at the request of the School District based on the eliminating of the student bussing within the city limits. Caltrans guidelines not satisfied. School funded Adult Crossing Guard placed.

August 1991

• Cherokee Lane at Hale Road - Council approved overhead flashing yellow beacon installation. Caltrans guidelines not satisfied.

October 1991

 Cherokee Lane at Hale Road - restudied intersection for adult crossing guards at the request of the School District during tracks with highest number of students. Caltrans guidelines not satisfied. Adult Crossing Guard funded by the School District.

June 1993

• Cherokee Lane at Hale Road - traffic signal activated.

November 1993

• Garfield Street at Eden Street - studied intersection for adult crossing guard. Caltrans guidelines not satisfied.



MULTI-WAY STOP SIGN WARRANTS


	INTERSECTION OF	: Garfield Street	and	Eden Street		
		March 7,1996	BY:	; R. Kiriu		
	Any of the following condi	tions may warrant a multi-way STOP sign	installation	n.		
1.		varranted and the need is urgent, the four- control traffic while arrangements are bein				
				Satisfied Not Satisfied	<u>x</u>	
2.	 An accident problem, as in by a multi-way stop instal include right angle and left 	dicated by five or more reported accidents lation in a 12-month period. Types of accitum collisions.	s of a type s cidents susc	susceptible of correction sceptible of correction		
		ec 1995		Number of correctible accidents	0	
	Total number of accidents	0		Satisfied Not Satisfied	<u>X</u>	
4	Hour Major Street 11: Minor Street 9: b. The coaverage minor street Hour Minor St Vehs 9: Pedestrians 118 Peds p	mbined vehicular and pedestrian volume fe at least 200 units per hour for the san street vehicular traffic of at least 30 second 5 82 74 66 63 133 74 er hour or 945 total needed to sat	103 68 from the mine eight hounds per veh	Highest eight hours		
4.		proach speed of the major street traffic ex warrant is 70 percent of the above requir		miles per nour, the		
				85-percentile speed 25 (prima facie) Not Satisfied Not Satisfied		
	A four-way STOP sign installation is a useful traffic control measure when other available means of					
		control are not adequate. It should not be used unless the volume of traffic on the intersecting roads is about equal and is undesirable at low volume intersections.				
				Traffic major street 60 %		
				Traffic minor street%		
Approved by:		Multi-way Stop Warrants Satisfied: yes no _X				
	Refere	nce: Caltrans Traffic Manual		Mar-96		



MULTI-WAY STOP SIGN WARRANTS

			Control Assessed			Ed. Oraș		
	INTERSECT		Central Avenue March 7, 1996			Eden Street R. Kiriu		
	Any of the following	g conditi	ons may warrant a multi-w	ay STOP sign installa	ation			
1.			rranted and the need is urg ontrol traffic while arranger					
						Satisfied	Not Satisfied X	
2.		p installa	icated by five or more repo tion in a 12-month period. urn collisions.				on	
	Time period Total number of acc	Jan - De cidents	22			Number of correctible Satisfied	Not Satisfied X	
3.			Il vehicular volume entering vehicles per hour for any e	ight hours of an aver	m all rage	day, and		
	Hour Major Street Minor Street	299 42	378 346 455 492 36 46 58 53			Highest eight hours Total volume Average per hour	a.m. to 3877 vehicles 485 vehicles	p.m.
		average	at least 200 units per ho reet vehicular traffic of at l	ur for the same eight	t hou	ırs with an average de	ay to	
	Minor St Vehs Pedestrians	42	36 46 58 53	73 91 82	المرزأ	Highest eight hours _ Average per hour Average per hour Average units per hou	60 vehicles 0 peds (EST)	p.m.
	140	Peds pe	rhour or 1,119 total r	needed to satisfy.		Satisfied	Not Satisfied X	
4.			roach speed of the major st warrant is 70 percent of the			niles per hour, the		
						85-percentile speed Satisfied	27 MP Not Satisfied X	H
		control a	vay STOP sign installation i are not adequate. It should equal and is undesirable at	not be used unless th	he v	olume of traffic on the		
						Traffic major street Traffic minor street		
	Approved by:			Multi-way Stop Wa	arrar	nts Satisfied: yes_	no <u>X</u>	
		Referen	ce: Caltrans Traffic Manual				Mar-96	

CENT-EDN.XLS



CITY COUNCIL

DAVID P. WARNER, Mayor PHILLIP A. PENNINO Mayor Pro Tempore RAY G. DAVENPORT STEPHEN J. MANN JACK A. SIEGLOCK

CITY OF LODI

CITY HALL, 221 WEST PINE STREET
P.O. BOX 3006
LODI, CALIFORNIA 95241-1910
(209) 333-6706
FAX (209) 333-6842

March 14, 1996

H. DIXON FLYNN
City Manager

JENNIFER M. PERRIN
City Clerk

RANDALL A. HAYS
City Attorney

SUBJECT: Heritage School Vicinity - Various Traffic Studies

Enclosed is a copy of background information on an item on the City Council agenda of Wednesday, March 20, 1996, at 7 p.m. The meeting will be held in the City Council Chamber, Carnegie Forum, 305 West Pine Street.

This item is on the regular calendar for Council discussion. You are welcome to attend.

If you wish to write to the City Council, please address your letter to City Council, City of Lodi, P. O. Box 3006, Lodi, California, 95241-1910. Be sure to allow time for the mail. Or, you may hand-deliver the letter to the City Clerk at 305 West Pine Street.

If you wish to address the Council at the Council meeting, be sure to fill out a speaker's card (available at the Carnegie Forum immediately prior to the start of the meeting) and give it to the City Clerk. If you have any questions about communicating with the Council, please contact Jennifer Perrin, City Clerk, at (209) 333-6702.

If you have any questions about the item itself, please call Paula Fernandez or Rick Kiriu at (209) 333-6706.

Jack L. Ronsko

Public Works Director

JLR/pmf

Enclosure

cc: City Clerk

MAILING LIST FOR NOTICE OF CITY COUNCIL MEETING REGARDING HERITAGE SCHOOL VICINITY - VARIOUS TRAFFIC STUDIES

Orginization	Name	Address
HERITAGE SCHOOL	PRINCIPAL	509 E. EDEN
	MARY GRAHAM	LODI CA 95240
HERITAGE SCHOOL	VICE PRINCIPAL BINDY	509 E EDEN
	GREWALL	LODI CA 95240
LODI UNIFIED	ACTING	1305 E VINE
SCHOOL DISTRICT	SUPERINTENDENT	LODI CA 95240
	DEL ALBERTI	
LODI UNIFIED	ADMIN DIR TO ELEM	1305 E VINE
SCHOOL DISTRICT	PRINCIPALS	LODI CA 95240
	PAT HILL	
	MELISSA OHM	509 E EDEN
		LODI CA 95240
	BARBARA MCKAY	425 EDEN
		LODI CA 95240
LUSD POLICE	DIRECTOR FRANK	1305 E VINE
SERVICES	BIGLOW	LODI CA 95240

LNCHERIT.DOC 3/14/96